Release Note for VigorAP 810

Firmware Version:	1.3.3
Release Type:	Normal
Applied Models:	VigorAP 810

With this high cost-efficiency VigorAP 810, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP 810, at the speed of 300Mbps. Easy install procedures allows users to setup a network environment in very short time - within minutes, even inexperienced users. Just follow the instructions given in this user manual, you can complete the setup procedure and release the power of this access point all by yourself!

New Features

- Support RootAP management (as a node).

Improvement

- Improved: Disable any 3DES ciphers.
- Improved: Modify DrayTek AP A-Band Channel List for Australia and Thailand.
- Improved: Add an option to enable / disable the WMM Capable setting on Wireless LAN >> Advanced Setting.
- Improved: Add an option to enable/disable the function of the Reset button on System Maintenance >> Management.
- Improved: Improved the wireless network connection security (CVE-2019-15126, CVE-2018-20679 and CVE-2011-2716).
- Improved: Add a note related to "To allow communication between clients with different SSIDs on different bands..." on Wireless LAN >> General Setup.
- Corrected: A display issue of SSID on Wireless LAN(5GHz)>> Station List.
- Corrected: An issue of failing to configure SSID with Open security over APM.
- Corrected: A display error issue of Wireless 5G Channel Load value on System Log.
- Corrected: An issue of password required for a wireless client when connecting to Vigor device via non-security setting.
- Corrected: An issue of unexpected dialog appeared after resetting VigorAP and accessing Wireless LAN (5GHz) configuration page.

Known Issue

- None.